

Comments from Highway and water superintendent

Mink Property. 4788 County road 16

1. The water service that is proposed for the barn I would suggest that the owner look to bring the water from the existing home to the barn verses a new water service. This is because the cost to tap the water main and bring it under the road will cost more than a typical directional drill. On the east side is a steep slope and the water main is on the edge of it. On the west side is another significant slope and there is not enough room to put the machine to drill across the road unless it was set up behind the barn. I am sure the county would not allow an open cut of the highway. If the property owner still wants a new water service I will need to provide the cost to them but it will not be what is on our fee schedule due to the constraints of the job.

2. Center point Apartments. Brickyard road.

This section of road where the entrance to the buildings was paved in May. Care must be taken to prevent any damage to the road. Must keep road clean of mud and stones from equipment. A parking area on the property would be very helpful instead of parking on the side of the road.

Jim Fletcher