



Patio Rehabilitation & Access Improvements

Site Plan Application Packet

July 16, 2021

Hyman Residence
4655 West Lake Road
Canandaigua, New York

Table of Contents

- 1-2 Existing Conditions Photographs
- 3 Rendered Site Plan

Sue
Steele
Landscape
Architecture
PLLC



Existing Steep Sloped Lawn (South Yard)



Existing Steep Sloped Lawn (South Yard)




Existing Steps to (South Yard/Leach Field)



Existing Lakeside Condition



Existing Paver Ramp to Stairs



Existing Patio and Lakeside Condition (North Yard)

Site Plan Review Package | Existing Conditions Photographs

4655 West Lake Road, Canandaigua New York

July 16, 2021 | Page 1



Existing Hazard Oak (north, heavy decay)



Existing Hazard Trees (to be removed)



Existing Hazard Oak (south, heavy decay)



Existing Shoreline Condition (dashed line - tram alignment)



Approximate Tram Alignment



Existing Patio and Shoreline Vegetation

Site Plan Review Package | Existing Conditions Photographs

4655 West Lake Road, Canandaigua New York

July 16, 2021 | Page 2

