



Patio Rehabilitation & Access Improvements

Site Plan Review Planning Board Meeting

August 24, 2021

Hyman Residence
4655 West Lake Road
Canandaigua, New York

Table of Contents

- 1-2 Existing Conditions Photographs
- 3-4 Rendered Site Plan
- 5-6 Illustrative Renderings

Sue
Steele
Landscape
Architecture
PLLC



Existing Steep Sloped Lawn (South Yard)



Existing Steep Sloped Lawn (South Yard)



Existing Steps to (South Yard/Leach Field)



Existing Lakeside Condition



Existing Paver Ramp to Stairs



Existing Patio and Lakeside Condition (North Yard)



Existing Hazard Oak (north, heavy decay)



Existing Hazard Trees (to be removed)



Existing Hazard Oak (south, heavy decay)




Existing Shoreline Condition (dashed line - tram alignment)




Approximate Tram Alignment



Existing Patio and Shoreline Vegetation





EXISTING CONDITION AT PATIO



EXISTING LAKEFRONT



EXISTING PATIO AND WALLS



View from existing deck to patio.



Fireplace and low walls.



Patio and tram access.



Access improvements at existing wood stairs.



Stair and sloped lawn access improvements (south yard).



Stair and sloped lawn access improvements (south yard).